


Location of screws as called
out on shop drawing.

Ubicacionde los tornillos como
lo muestra el diseño



#10 Screws @ each end and 12" o.c.

Tornillos #10 a cada orilla ya 12" del centro

Two (2) #10 Screws @ each stud.
Locate 1" from top and bottom.
Screw through Header, Track, and Stud.

2 Tornillos #10 sms a cada stud
Ubicar 1" de la parte de arriba y de abajo

FrameMax, Inc.
13915 Danielson Street
Suite 100
Poway, CA 92064

Phone: 858 486-7200
Fax: 909 486-7220
www.frame-max.com

FRAMEMAX

FM-07-109-JHA
JEWISH HOME

JHA-5

L-Header & Cripple Attachment

FRAMEMAX